

Необходимые инструменты:

Цанговый нож со сменными лезвиями, пинцет, плоскогубцы, кусачки, надфили, набор сверел 0,3-1мм, паяльник с регулятором.

Необходимые материалы:

Столярный клей, цианокрилатный клей (супер-клей), наждачная бумага. Краски акриловые (черная полуматовая, золотая, медная)

Набор не рекомендуется детям младше 14 лет.

При работе с режущими инструментами требуется наблюдение взрослых.

Будьте осторожны при использовании цианокрилатного Детали следует отделять от пластины ножом. Не отделяйте сразу все детали от пластин, только по мере необходимости.

Места среза деталей зачистите ножом или наждачной бумагой.

С видимых торцов деталей рекомендуется удалить нагар. Сборку модели производите согласно инструкции. Для удобства каждая деталь обозначена индексом, соответствующему индексу пластины.

Расшифровка условных обозначений



Вспомогательный знак, когда детали требуется склеить между собой только в определенных местах, либо если в этапе стоит запрет на использование клея.




Запрет на склеивание (целиком в этапе сборки, либо на определенные детали)



Обозначение сборочной единицы. Ее номер соответствует номеру этапа в котором она собирается.



Деталь с данным знаком требует снятие малки. Пример:





Детали D50-D72 требуется срезать по краю обшивки.



Индекс L соответствует левому борту модели, R правому. В инструкции нумеруются только детали одного борта, детали второго борта установить по аналогии.



Индекс W обозначает склеивание детали из 2 половинок, для придания требуемой толщины.



Required Tools:

Hobby knife with blades, tweezers, pliers, wire cutters, small files, 0.3mm-1mm drill bits, soldering iron.

Required supplies:

Carpenter's glue (PVA), cyanoacrylate (CA) glue, sandpaper, acrylic paints (semi-matte black, gold and copper).

The kit is not recommended for children younger than 14 years old.

Adult supervision is required when working with cutting tools.

Be careful when using cyanoacrylate glue!

Parts should be removed from plates using a knife. Do not remove all parts at the same time, remove only the ones that are required at the moment.

Small tabs left in spots where parts were connected to plates should be trimmed flush using a hobby knife or a sanding block

We recommend sanding edges to remove burned oils from laser cutting.

Assemble the model according to the instructions. For convenience, each part number contains corresponding

plate's letter code.

Explanation of symbols



Auxiliary symbol for cases when parts need to be glued together only in specific spots or when gluing is required in a "no glue" stage.




Don't use glue (during an entire stage or for specified parts)



Assembly unit. Its number corresponds to the stage during which it is assembled.



Parts with this symbol must be beveled. Example:





Parts D50-D72 should be cut flush with the edge of the hull.




The label L corresponds to the port side of the model, R to the starboard. Only one side is shown in the instructions, the other side is assembled in a similar fashion.




The label W denotes parts that are glued together using 2 halfs to obtain the required thickness.

4 Пластина A (часть 1) Plate A (part 1) A7 Α9 A10 A12 A11 A2 24 23 25 26 A26 A25 A23 A24 A2 F0503-AN12A1 A80 R Пластина A (часть 2) Palate A (part 2) A15 A17 A14 A16 A13 A3 L A6 L D J 28 \Box 27 A6 R A28 A29 A27 А3 F0503-AN12A2 Пластина A (часть 3) Plate A (part 3) A19 A18 **A8** A21 a A1 A22 A20 A4 R A5 R 22 A4 L A5 L ₹ A1 F0503-AN12A3


Пластина В / Plate В




Пластина С / Plate C




Пластина D / Plate D




Пластина E / Plate E



Пластина G / Plate G




Пластина J / Plate B




Пластина H / Plate B



Пластины F / Plate F







Пластина Р / Plate P



Деталь Z183 / Detail Z183

Деталь Z41 / Detail Z41

Деталь Z179 / Detail Z179

Отдельные детали / Other details

| No and the state of the state o | | | |
|--|-----------------------------------|---------------|---------------------|
| No. | Материал / Material | Размер / Size | Количество / Amount |
| S30 | Смола / Resin | - | 1 |
| S31 | Смола / Resin | - | 1 |
| S32 | Смола / Resin | - | 1 |
| S34 | Смола / Resin | - | 1 |
| S35 | Смола / Resin | - | 1 |
| S36 | Смола / Resin | - | 1 |
| Z94 | Проволока 0.6мм / Wire 0.6mm | 200мм | 1 |
| Z103 | Смола или латунь / Resin or brass | - | 1 |
| Z105 | Дерево / Wood | - | 1 |
| Z106 | Дерево / Wood | - | 1 |
| Z107 | Дерево / Wood | - | 1 |
| Z139 | Дерево / Wood | - | 1 |
| Z140 | Проволока 0.4мм / Wire 0.4mm | 200мм | 1 |
| Z148 | Проволока 1мм / Wire 1mm | 200мм | 1 |
| Z152 | Дерево / Wood | - | 1 |
| Z182 | Латунь / Brass | - | 1 |
| Z187 | Перкаль / Percale | - | 1 |
| Z0.2 | Нить 0,2мм /Thread 0.2mm | 0.5м | 1 |
| Z0.4 | Нить 0,4мм /Thread 0.4mm | 1м | 1 |
| Z0.6 | Нить 0,6мм /Thread 0.6mm | 1м | 1 |

